

Decimal (mm)	Sizes	Decimal (ins)	Decimal (mm)	Sizes	Decimal (ins)	Decimal (mm)	Sizes	Decimal (ins)	Decimal (mm)	Sizes	Decimal (ins)	Decimal (mm)	Sizes	Decimal (ins)
.794	1/32	.0312	2.383	3/32	.0938	4.700	13	.1850	7.366	L	.2900	12.000		.4724
.800		.0315	2.400		.0945	4.750		.1870	7.400		.2913	12.304	31/64	.4844
.813	67	.0320	2.438	41	.0960	4.763	3/16	.1875	7.493	M	.2950	12.500		.4921
.838	66	.0330	2.450		.0965	4.800	12	.1890	7.500		.2953	112.700	1/2	.5000
.851		.0335	2.489	40	.0980	4.850	11	.1910	7.541	19/64	.2969	13.000		.5118
.889	65	.0350	2.500		.0984	4.900		.1929	7.600		.2992	13.096	33/64	.5156
.900		.0354	2.527	39	.0995	4.915	10	.1935	7.671	N	.3020	13.492	17/32	.5312
.914	64	.0360	2.578	38	.1015	4.978	9	.1960	7.700		.3031	13.500		.5315
.940	63	.0370	2.600		.1024	5.000		.1969	7.750		.3051	13.891	35/64	.5469
.950		.0374	2.642	37	.1040	5.055	8	.1990	7.800		.3071	14.000		.5512
.965	62	.0380	2.700		.1063	5.100		.2008	7.900		.3110	14.287	9/16	.5625
.991	61	.0390	2.705	36	.1065	5.105	7	.2010	7.938	5/16	.3125	14.500		.5709
1.000		.0394	2.750		.1083	5.159	13/64	.2031	8.000		.3150	14.684	37/64	.5781
1.016	60	.0400	2.779	7/64	.1094	5.182	6	.2040	8.026	O	.3160	15.000		.5906
1.041	59	.0410	2.794	35	.1100	5.200		.2047	8.100		.3189	15.083	19/32	.5938
1.049		.0413	2.800		.1102	5.220	5	.2055	8.200		.3228	15.479	39/64	.6094
1.067	58	.0420	2.819	34	.1110	5.250		.2067	8.204	P	.3230	15.500		.6102
1.092	57	.0430	2.870	33	.1130	5.300		.2087	8.250		.3248	15.875	5/8	.6250
1.100		.0433	2.900		.1142	5.309	4	.2090	8.300		.3268	16.000		.6299
1.151		.0453	2.946	32	.1160	5.400		.2126	8.334	21/64	.3281	16.271	41/64	.6406
1.181	56	.0465	3.000		.1181	5.410	3	.2130	8.400		.3307	16.500		.6496
1.191	3/64	.0469	3.048	31	.1200	5.500		.2165	8.433	Q	.3320	16.667	21/32	.6562
1.200		.0472	3.100		.1220	5.558	7/32	.2188	8.500		.3346	17.000		.6693
1.250		.0492	3.175	1/8	.1250	5.600		.2205	8.600		.3386	17.066	43/64	.6719
1.300		.0512	3.200		.1260	5.613	2	.2210	8.611	R	.3390	17.463	11/16	.6875
1.321	55	.0520	3.250		.1280	5.700		.2244	8.700		.3425	17.500		.6890
1.349		.0531	3.264	30	.1285	5.750		.2264	8.733	11/32	.3438	17.859	45/64	.7031
1.397	54	.0550	3.300		.1299	5.791	1	.2280	8.750		.3445	18.000		.7087
1.400		.0551	3.400		.1339	5.800		.2283	8.800		.3465	18.258	13/32	.7188
1.450		.0571	3.454	29	.1360	5.900		.2323	8.839	S	.3480	18.500		.7283
1.500		.0591	3.500		.1378	5.944	A	.2340	8.900		.3504	18.654	47/64	.7344
1.511	53	.0595	3.569	28	.1405	5.954	15/64	.2344	9.000		.3543	19.000		.7480
1.550		.0610	3.571	9/64	.1406	6.000		.2362	9.093	T	.3580	19.050	3/4	.7500
1.588	1/16	.0625	3.600		.1417	6.045	B	.2380	9.100		.3583	19.446	49/64	.7656
1.600		.0630	3.658	27	.1440	6.100		.2402	9.129	23/64	.3594	19.500		.7677
1.613	52	.0635	3.700		.1457	6.147	C	.2420	9.200		.3622	19.842	25/32	.7812
1.650		.0650	3.734	26	.1470	6.200		.2441	9.250		.3642	20.000		.7874
1.700		.0669	3.750		.1476	6.248	D	.2460	9.300		.3661	20.241	51/64	.7969
1.702	51	.0670	3.797	25	.1495	6.250		.2461	9.347	U	.3680	20.500		.8071
1.750		.0689	3.800		.1496	6.300		.2480	9.400		.3701	20.638	13/16	.8125
1.778	50	.0700	3.861	24	.1520	6.350	E	.2500	9.500		.3740	21.000		.8268
1.800		.0709	3.900		.1536	6.350	1/4	.2500	9.525	3/8	.3750	21.034	53/64	.8281
1.850		.0728	3.912	23	.1540	6.400		.2520	9.576	V	.3770	21.433	27/32	.8438
1.854	49	.0730	3.962	5/32	.1562	6.500		.2559	9.600		.3780	21.500		.8465
1.900		.0748	3.988	22	.1570	6.528	F	.2570	9.700		.3819	21.829	55/64	.8594
1.930	48	.0760	4.000		.1575	6.600		.2598	9.750		.3839	22.000		.8661
1.950		.0768	4.039	21	.1590	6.629	G	.2610	9.800		.3858	22.225	7/8	.8750
1.984	5/64	.0781	4.089	20	.1610	6.700		.2638	9.804	W	.3860	22.500		.8858
1.994	47	.0785	4.100		.1614	6.746	17/64	.2656	9.900		.3898	22.261	57/64	.8906
2.000		.0787	4.200		.1654	6.750		.2657	9.921	25/64	.3906	23.000		.9055
2.050		.0807	4.216	19	.1660	6.756	H	.2660	10.000		.3937	23.017	29/32	.9062
2.057	46	.0810	4.250		.1673	6.800		.2677	10.084	X	.3970	23.416	59/64	.9219
2.083	45	.0820	4.300		.1693	6.900		.2717	10.262	Y	.4040	23.500		.9252
2.100		.0827	4.305	18	.1695	6.909	I	.2720	10.317	13/32	.4062	23.813	15/16	.9375
2.150		.0846	4.366	11/64	.1719	7.000		.2756	10.490	Z	.4130	24.000		.9449
2.184	44	.0860	4.394	17	.1730	7.036	J	.2770	10.500		.4134	24.209	61/64	.9531
2.200		.0866	4.400		.1732	7.100		.2795	10.716	27/64	.4219	24.500		.9646
2.250		.0886	4.496	16	.1770	7.137	K	.2810	11.000		.4331	24.608	31/32	.9688
2.260	43	.0890	4.500		.1772	7.142	9/32	.2812	11.113	7/16	.4375	25.000		.9843
2.300		.0906	4.572	15	.1800	7.200		.2835	11.500		.4528	25.004	63/64	.9844
2.350		.0925	4.600		.1811	7.250		.2854	11.509	29/64	.4531	25.400		1.000
2.375	42	.0935	4.623	14	.1820	7.300		.2874	11.908	18/32	.4688			